


8pcs	18pcs	2pcs	5pcs	40pcs	33pcs	2pcs	2pcs	4pcs	1pc	2pcs
										
										3pcs


ITEM NO.	DESCRIPTION	QTY
1	2"x10" Wood Not Included	2
2	2"x10" Wood Not Included	3
3	Top "L" Bracket	2
4	Leg	4
5	5/16" x 2-1/4" Carriage Bolt (Zinc)	18
6	5/16" Zinc Plated Washer	40
7	5/16" Hex Nut (Zinc)	33
8	table brace	2
9	5/16" x 3-3/4" Carriage Bolt (Zinc)	8
10	5/16" x 4-3/8" Machine Bolt (Zinc)	2
11	5/16" x 2-3/8" Machine Bolt (Zinc)	5
12	Center U Channel	1






Dimensions For Drilling Seat & Table Top Planks

Seat Drill Pattern



*Dimensions provided are for reference only. Please verify measurements directly with the frame before drilling.


Table Top Drill Pattern




*Dimensions provided are for reference only. Please verify measurements directly with the frame before drilling.

ITEM NO.	DESCRIPTION	QTY
1	2"x10" Wood Not Included	2
2	2"x10" Wood Not Included	3
3	Top "L" Bracket	2
4	Leg	4
5	5/16" x 2-1/4" Carriage Bolt (Zinc)	18
6	5/16" Zinc Plated Washer	40
7	5/16" Hex Nut (Zinc)	33
8	table brace	2
9	5/16" x 3-3/4" Carriage Bolt (Zinc)	8
10	5/16" x 4-3/8" Machine Bolt (Zinc)	2
11	5/16" x 2-3/8" Machine Bolt (Zinc)	5
12	Center U Channel	1

Step 1.



Step 2.



Step 3.

