




 72" 2pcs  72"		 1pc 
22pcs	4pcs	1pcs	2pcs	28pcs	25pcs	3pcs	2pcs	2pcs


ITEM NO.	DESCRIPTION	QTY
1	2" x 10" Wood Not Supplied	3
2	2" x 10" Wood Not Supplied	2
3	Leg	2
4	5/16" x 1" Hex Head Bolt (Zinc)	2
5	5/16" Zinc Plated Washer	28
6	5/16" Hex Nut (Zinc)	25
7	Center U Channel	1
8	Table brace	2
9	5/16" x 2-1/4" Carriage Bolt (Zinc)	22
10	5/16"x2-1/4" Round-head hex socket screw(zinc)	4
11	5/16"x2-1/4" Hex Head Bolt (Zinc)	1






Dimensions For Drilling Seat & Table Top Planks

Seat Drill Pattern



*Dimensions provided are for reference only. Please verify measurements directly with the frame before drilling.


Table Top Drill Pattern




*Dimensions provided are for reference only. Please verify measurements directly with the frame before drilling.

ITEM NO.	DESCRIPTION	QTY
1	2" x 10" Wood Not Supplied	3
2	2" x 10" Wood Not Supplied	2
3	Leg	2
4	5/16" x 1" Hex Head Bolt (Zinc)	2
5	5/16" Zinc Plated Washer	28
6	5/16" Hex Nut (Zinc)	25
7	Center U Channel	1
8	Table brace	2
9	5/16" x 2-1/4" Carriage Bolt (Zinc)	22
10	5/16"x2-1/4" Round-head hex socket screw(zinc)	4
11	5/16"x2-1/4" Hex Head Bolt (Zinc)	1


Step 1



Step 2



Step 3



Note: Number 10 is used on the outside of the chair.